

切削参数参考表

Recommended Milling Conditions

加工材料 Work Material			高硬度钢 Hardened Steels STAVAX · SKD61 (~52HRC)				高硬度钢 Hardened Steels SKD11 · ELMAX (~62HRC)				高速钢 High Speed Steels SKH · HAP (~68HRC)			
(R)球头半径 Radius	颈角 Neck Taper Angle	颈长 Under Neck Length	切深量 Depth of Cut		进给速度 Feed	主轴转速 Spindle Speed	切深量 Depth of Cut		进给速度 Feed	主轴转速 Spindle Speed	切深量 Depth of Cut		进给速度 Feed	主轴转速 Spindle Speed
			ap mm	ae mm	mm/min	min ⁻¹	ap mm	ae mm	mm/min	min ⁻¹	ap mm	ae mm	mm/min	min ⁻¹
0.1	30'	1.5	0.003	0.005	140	40,000	0.003	0.003	120	40,000	0.002	0.003	100	40,000
		2	0.003	0.003	120	40,000	0.002	0.003	100	40,000	0.002	0.002	80	40,000
	1°	1.5	0.003	0.005	160	40,000	0.003	0.003	140	40,000	0.002	0.003	120	40,000
		2	0.003	0.003	140	40,000	0.002	0.003	120	40,000	0.002	0.002	90	40,000
	1° 30'	1.5	0.003	0.005	200	40,000	0.003	0.003	160	40,000	0.002	0.003	140	40,000
		2	0.003	0.003	160	40,000	0.002	0.003	140	40,000	0.002	0.002	100	40,000
2°	1.5	0.003	0.005	240	40,000	0.003	0.003	200	40,000	0.002	0.003	160	40,000	
	2	0.003	0.003	200	40,000	0.002	0.003	160	40,000	0.002	0.002	120	40,000	
0.15	30'	2	0.005	0.005	200	40,000	0.005	0.005	160	40,000	0.003	0.005	120	40,000
		3	0.003	0.005	160	40,000	0.003	0.003	120	40,000	0.002	0.003	100	40,000
	1°	2	0.005	0.005	240	40,000	0.005	0.005	200	40,000	0.003	0.005	160	40,000
		3	0.003	0.005	200	40,000	0.003	0.003	160	40,000	0.002	0.003	120	40,000
	1° 30'	2	0.005	0.005	320	40,000	0.005	0.005	240	40,000	0.003	0.005	200	40,000
		3	0.003	0.005	240	40,000	0.003	0.003	200	40,000	0.002	0.003	160	40,000
2°	2	0.005	0.005	400	40,000	0.005	0.005	300	40,000	0.003	0.005	240	40,000	
	3	0.003	0.005	300	40,000	0.003	0.003	240	40,000	0.002	0.003	180	40,000	
0.2	30'	3	0.007	0.01	320	40,000	0.005	0.01	240	40,000	0.005	0.005	160	40,000
		4	0.005	0.005	240	36,000	0.005	0.005	180	36,000	0.003	0.005	120	36,000
	1°	3	0.007	0.01	400	40,000	0.005	0.01	300	40,000	0.005	0.005	200	40,000
		4	0.005	0.005	320	36,000	0.005	0.005	240	36,000	0.003	0.005	160	36,000
	1° 30'	3	0.007	0.01	480	40,000	0.005	0.01	360	40,000	0.005	0.005	240	40,000
		4	0.005	0.005	400	36,000	0.005	0.005	320	36,000	0.003	0.005	200	36,000
2°	3	0.007	0.01	540	40,000	0.005	0.01	400	40,000	0.005	0.005	300	40,000	
	4	0.005	0.005	480	36,000	0.005	0.005	360	36,000	0.003	0.005	240	36,000	
0.25	30'	4	0.01	0.01	400	36,000	0.005	0.01	320	36,000	0.005	0.005	240	36,000
		5	0.005	0.01	320	32,000	0.005	0.005	240	32,000	0.003	0.005	160	32,000
	1°	4	0.01	0.01	480	36,000	0.005	0.01	400	36,000	0.005	0.005	300	36,000
		5	0.005	0.01	400	32,000	0.005	0.005	320	32,000	0.003	0.005	240	32,000
	1° 30'	4	0.01	0.01	640	36,000	0.005	0.01	480	36,000	0.005	0.005	360	36,000
		5	0.005	0.01	540	32,000	0.005	0.005	400	32,000	0.003	0.005	300	32,000
2°	4	0.01	0.01	720	36,000	0.005	0.01	540	36,000	0.005	0.005	400	36,000	
	5	0.005	0.01	640	32,000	0.005	0.005	480	32,000	0.003	0.005	360	32,000	
0.3	30'	5	0.01	0.01	480	36,000	0.005	0.01	400	36,000	0.005	0.005	300	36,000
		6	0.005	0.01	400	32,000	0.005	0.005	360	32,000	0.003	0.005	240	32,000
	1°	5	0.01	0.01	640	36,000	0.005	0.01	480	36,000	0.005	0.005	400	36,000
		6	0.005	0.01	540	32,000	0.005	0.005	400	32,000	0.003	0.005	300	32,000
	1° 30'	5	0.01	0.01	800	36,000	0.005	0.01	640	36,000	0.005	0.005	480	36,000
		6	0.005	0.01	720	32,000	0.005	0.005	540	32,000	0.003	0.005	400	32,000
2°	5	0.01	0.01	900	36,000	0.005	0.01	720	36,000	0.005	0.005	540	36,000	
	6	0.005	0.01	800	32,000	0.005	0.005	640	32,000	0.003	0.005	480	32,000	

◎ 高硬度钢~52
Hardened Steel HRC H◎ 高硬度钢~60
Hardened Steel HRC H◎ 高硬度钢~65
Hardened Steel HRC H◎ 高硬度钢~70
Hardened Steel HRC H



加工材料 Work Material			高硬度钢 Hardened Steels STAVAX · SKD61 (~52HRC)				高硬度钢 Hardened Steels SKD11 · ELMAX (~62HRC)				高速钢 High Speed Steels SKH · HAP (~68HRC)				
(R)球头半径 Radius	颈角 Neck Taper Angle	颈长 Under Neck Length	切深量 Depth of Cut		进给速度 Feed	主轴转速 Spindle Speed	切深量 Depth of Cut		进给速度 Feed	主轴转速 Spindle Speed	切深量 Depth of Cut		进给速度 Feed	主轴转速 Spindle Speed	
			ap mm	ae mm	mm/min	min ⁻¹	ap mm	ae mm	mm/min	min ⁻¹	ap mm	ae mm	mm/min	min ⁻¹	
0.5	30'	8	0.01	0.02	900	20,000	0.01	0.02	800	20,000	0.01	0.01	640	20,000	
		10	0.01	0.02	720	16,000	0.005	0.01	640	16,000	0.005	0.005	480	16,000	
	1°	8	0.01	0.02	1,000	20,000	0.01	0.02	900	20,000	0.01	0.01	800	20,000	
		10	0.01	0.02	800	16,000	0.005	0.01	720	16,000	0.005	0.005	640	16,000	
	1° 30'	8	0.01	0.02	1,200	20,000	0.01	0.02	1,000	20,000	0.01	0.01	900	20,000	
		10	0.01	0.02	900	16,000	0.005	0.01	800	16,000	0.005	0.005	720	16,000	
	2°	8	0.01	0.02	1,400	20,000	0.01	0.02	1,200	20,000	0.01	0.01	1,000	20,000	
		10	0.01	0.02	1,000	16,000	0.005	0.01	900	16,000	0.005	0.005	800	16,000	
	0.75	30'	10	0.02	0.02	800	16,000	0.015	0.02	900	16,000	0.01	0.015	600	16,000
			15	0.01	0.02	540	12,000	0.01	0.01	480	12,000	0.005	0.01	400	12,000
1°		10	0.02	0.02	900	16,000	0.015	0.02	1,000	16,000	0.01	0.015	720	16,000	
		15	0.01	0.02	680	12,000	0.01	0.01	600	12,000	0.005	0.01	540	12,000	
1° 30'		10	0.02	0.02	1,200	20,000	0.015	0.02	1,000	20,000	0.01	0.015	900	20,000	
		15	0.01	0.02	900	16,000	0.01	0.01	800	16,000	0.005	0.01	720	16,000	
2°		10	0.02	0.02	1,400	20,000	0.015	0.02	1,200	20,000	0.01	0.015	1,000	20,000	
		15	0.01	0.02	1,000	16,000	0.01	0.01	900	16,000	0.005	0.01	800	16,000	
1		30'	16	0.02	0.03	720	12,000	0.015	0.03	540	12,000	0.01	0.02	400	12,000
			20	0.02	0.02	400	8,000	0.01	0.02	360	8,000	0.01	0.01	240	8,000
	1°	16	0.02	0.03	1,000	16,000	0.015	0.03	800	16,000	0.01	0.02	600	16,000	
		20	0.02	0.02	600	12,000	0.01	0.02	540	12,000	0.01	0.01	400	12,000	
	1° 30'	16	0.02	0.03	1,200	20,000	0.015	0.03	1,000	20,000	0.01	0.02	800	20,000	
		20	0.02	0.02	900	16,000	0.01	0.02	800	16,000	0.01	0.01	600	16,000	
	2°	16	0.02	0.03	1,400	20,000	0.015	0.03	1,200	20,000	0.01	0.02	1,000	20,000	
		20	0.02	0.02	1,000	16,000	0.01	0.02	900	16,000	0.01	0.01	800	16,000	
	备注 Notes			<p>※1 切深量为中精加工、精加工时的最大值。请根据机床刚性和要求精度进行调整。</p> <p>※2 预加工（中精加工）时请注意精加工余量相对于加工面需保持均匀。</p> <p>※3 发生振刀时，请以相同的比率降低主轴转速和进给速度。此外，主轴转速过低时，也以相同的比率降低。</p> <p>※4 R角等负载大的加工部位，请特别注意参数设定和刀路轨迹等。</p> <p>※5 加工深沟时，请充分注意冷却液的供油及排屑是否顺畅。</p> <p>※6 建议使用油雾冷却方式。</p> <p>※1 Max. Depth of Cut for semi-finishing and finishing. Adjust milling conditions depending on the rigidity of the machine and desired accuracy.</p> <p>※2 Obtain uniform stock amount on the cutting surface in the pre-stage cutting (semi-finishing).</p> <p>※3 Reduce both spindle speed and feed at same rate for chattering and also for insufficient spindle speed of a machine.</p> <p>※4 Required careful set up of milling conditions, tool path and etc. at cutting parts, such as corners where will become overloaded.</p> <p>※5 Coolant supply and chip disposal in the deep portion are very important.</p> <p>※6 Oil mist coolant is recommended.</p>											

H ~52高硬度钢
HRC Hardened SteelH ~60高硬度钢
HRC Hardened SteelH ~65高硬度钢
HRC Hardened SteelH ~70高硬度钢
HRC Hardened Steel

使用注意事项

Points in Use

加工环境 Advice on Cutting Environment

- 刀具偏摆量越小越好。
Minimize the deflection of cutting edge.

- 掌握机床主轴的伸缩量以及机床的水平状态，需要时采取恰当的措施。

To understand the nature of the expansion of the main spindle and machine posture transformation, and take measures against them.

精加工量(余量) Advice on Finishing Allowance (stock amount)

- 使用小径CBN铣刀时，精加工量(余量)均匀性非常重要。
When using small CBN End Mill, uniform finishing allowance (stock amount) is important.
- 粗加工·中精加工使用刀具磨损过大时，中精加工和精加工的余量会变大，从而影响刀具寿命和加工精度，所以预加工时留有均匀的加工余量非常重要。

When tool is used on roughing and semi-finishing and it has a big abrasion, finishing allowance (stock amount) on semi-finishing and finishing is increasing and it affects tool life and cutting accuracy. Therefore, it is important to get uniform stock amount in the pre-stage cutting.

