

加工材料 Work Material	高硬度钢・高速钢 Hardened Steels・High Speed Steels SKD・SKH・HAP (~68HRC)					
	切深量 Depth of Cut		一般参数 Normal Speed		高速参数 High Speed	
(R)球头半径 Radius			进给速度 Feed	主轴转速 Spindle Speed	进给速度 Feed	主轴转速 Spindle Speed
$\Delta p$ mm	$\Delta e$ mm	mm/min	min <sup>-1</sup>	mm/min	min <sup>-1</sup>	
0.1 ~0.2	0.005	0.01	600	20,000	1,500	50,000
0.25~0.3	0.01	0.01	800		2,000	
0.4 ~0.6	0.01	0.02	1,200		3,000	
0.7 ~0.8	0.01	0.02	1,600		4,000	
0.9 ~1	0.02	0.05	2,000		5,000	

备 注  
Notes

- ※1 切深量的 $\Delta p$ 表示轴向切深量， $\Delta e$ 表示步距量。
- ※2 超精密加工专用的铣刀。请在完成钨钢铣刀的精加工后使用。
- ※3 请将切深量固定为切削参数参考表内的数值使用。
- ※4 R角加工时请特别注意参数设定（刀路轨迹等）。
- ※5 建议使用油雾冷却方式。
- ※6 建议使用刚性较大的铣刀刀柄和机床。
- ※1 Depth of Cut:  $\Delta p$ =Axial Depth of Cut /  $\Delta e$ =Radial Depth of Cut.
- ※2 SFB200 is a Super-Finish Ball End Mill recommended to use after the finish process of carbide end mill.
- ※3 Cutting depth must be fixed all through the milling process according to the recommended milling conditions.
- ※4 Pay a special attention when choosing tool path and deciding a milling condition for corner milling.
- ※5 We recommend using oil mist coolant.
- ※6 Machine, tool chuck must be sufficiently accurate.


长颈  
Long Neck无涂层  
Non-Coating球头  
Ball

## 加工案例1 Machining Case 1

## 反射板 Reflector

- 加工材料：ELMAX 60HRC Work material : ELMAX 60HRC
- 冷却方式：油雾 Coolant : Oil mist
- 总加工时间：19小时10分钟 Total machining time : 19hr 10min

加工工序 Process	粗加工 Roughing	中精加工 Semi-finishing	精加工 Finishing
使用刀具 Tool	MSBH230 R0.2	SSBL200 R0.2x1.2	SFB200 R0.2
主轴转速 [min <sup>-1</sup> ] Spindle speed		40,000	
进给速度 [mm/min] Feed	800	700	400
切深量 $\Delta p \times \Delta e$ [mm] Depth of cut	0.015×0.05	0.005×0.01	0.004×0.002
加工时间 Machining time	3小时23分钟 3hr 23min	2小时10分钟 2hr 10min	13小时37分钟 13hr 37min

工件尺寸：20×20mm  
Work size : 20×20mm

- H ~52高硬度钢  
HRC Hardened Steel
- H ~60高硬度钢  
HRC Hardened Steel
- H ~65高硬度钢  
HRC Hardened Steel
- H ~70高硬度钢  
HRC Hardened Steel

## 使用注意事项

## 加工环境 Advice on Cutting Environment

- 刀具偏摆量越小越好。  
Minimize the deflection of cutting edge.
- 掌握机床主轴的伸缩量以及机床的水平状态，需要时采取恰当的措施。  
To understand the nature of the expansion of the main spindle and machine posture transformation, and take measures against them.

## 精加工量(余量) Advice on Finishing Allowance (stock amount)

- 使用小径CBN铣刀时，精加工量(余量)均匀性非常重要。  
When using small CBN End Mill, uniform finishing allowance (stock amount) is important.
- 粗加工・中精加工使用刀具磨损过大时，中精加工和精加工的余量会变大，从而影响刀具寿命和加工精度，所以预加工时留有均匀的加工余量非常重要。  
When tool is used on roughing and semi-finishing and it has a big abrasion, finishing allowance (stock amount) on semi-finishing and finishing is increasing and it affects tool life and cutting accuracy. Therefore, it is important to get uniform stock amount in the pre-stage cutting.

## Points in Use

